Montana Board of Oil and Gas Conservation <u>Environmental Assessment</u>

Operator: Continental Resources, Inc.
Well Name/Number: Buckley 1-9H Location: SE SW Section 9 T25N R56E
County: Richland, MT; Field (or Wildcat) W/C
Air Quality
(possible concerns)
Long drilling time: No, 30 to 40 days drilling time.
Unusually deep drilling (high horsepower rig): Yes, triple derrick, 1000 HP drilling rig to
drill a single lateral Bakken Formation horizontal well, 19,468'MD/9,939'TVD.
Possible H2S gas production: Slight.
In/near Class I air quality area: No not in a class I air quality area.
Air quality permit for flaring/venting (if productive): Yes, DEQ air quality permit required
under 75-2-211.
Mitigation:
_X Air quality permit (AQB review)
X Gas plants/pipelines available for sour gas
Special equipment/procedures requirements
Other:
Comments: No special concerns – using triple rig to drill a single lateral
Bakken Formation horizontal well, 19,468'MD/9,939'TVD.
Water Quality
(possible concerns)
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil
(possible concerns) Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil
Salt/oil based mud: <u>Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole</u> . Brine water in the horizontal lateral
Salt/oil based mud: <u>Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole.</u> Brine water in the horizontal lateral. High water table: <u>No high water table anticipated.</u>
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about 1/4 of a mile to the east are unnamed ephemeral tributary drainages to Hardscrabble Creek. Within these ephemeral drainages is a stock pond, about 3/8 of a
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about 1/4 of a mile to the east are unnamed ephemeral tributary drainages to
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about 1/4 of a mile to the east are unnamed ephemeral tributary drainages to Hardscrabble Creek. Within these ephemeral drainages is a stock pond, about 3/8 of a mile to the northeast from this location. Water well contamination: No, closest stock water wells are about 3/4 of a mile to the
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about 1/4 of a mile to the east are unnamed ephemeral tributary drainages to Hardscrabble Creek. Within these ephemeral drainages is a stock pond, about 3/8 of a mile to the northeast from this location. Water well contamination: No, closest stock water wells are about 3/4 of a mile to the east, 7/8 of a mile to the northwest and 1 mile to the northwest from this location.
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about 1/4 of a mile to the east are unnamed ephemeral tributary drainages to Hardscrabble Creek. Within these ephemeral drainages is a stock pond, about 3/8 of a mile to the northeast from this location. Water well contamination: No, closest stock water wells are about 3/4 of a mile to the
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about 1/4 of a mile to the east are unnamed ephemeral tributary drainages to Hardscrabble Creek. Within these ephemeral drainages is a stock pond, about 3/8 of a mile to the northeast from this location. Water well contamination: No, closest stock water wells are about 3/4 of a mile to the east, 7/8 of a mile to the northwest and 1 mile to the northwest from this location. Surface hole will be drilled with freshwater and freshwater muds to 1900'. Surface casing will be cemented to surface from 1900'.
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about ½ of a mile to the east are unnamed ephemeral tributary drainages to Hardscrabble Creek. Within these ephemeral drainages is a stock pond, about 3/8 of a mile to the northeast from this location. Water well contamination: No, closest stock water wells are about 3/4 of a mile to the east, 7/8 of a mile to the northwest and 1 mile to the northwest from this location. Surface hole will be drilled with freshwater and freshwater muds to 1900'. Surface casing will be cemented to surface from1900'. Porous/permeable soils: No, sandy clay soils.
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about 1/4 of a mile to the east are unnamed ephemeral tributary drainages to Hardscrabble Creek. Within these ephemeral drainages is a stock pond, about 3/8 of a mile to the northeast from this location. Water well contamination: No, closest stock water wells are about 3/4 of a mile to the east, 7/8 of a mile to the northwest and 1 mile to the northwest from this location. Surface hole will be drilled with freshwater and freshwater muds to 1900'. Surface casing will be cemented to surface from1900'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No Class I stream drainages in the area of review.
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about 1/4 of a mile to the east are unnamed ephemeral tributary drainages to Hardscrabble Creek. Within these ephemeral drainages is a stock pond, about 3/8 of a mile to the northeast from this location. Water well contamination: No, closest stock water wells are about 3/4 of a mile to the east, 7/8 of a mile to the northwest and 1 mile to the northwest from this location. Surface hole will be drilled with freshwater and freshwater muds to 1900'. Surface casing will be cemented to surface from1900'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No Class I stream drainages in the area of review. Mitigation:
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about ¼ of a mile to the east are unnamed ephemeral tributary drainages to Hardscrabble Creek. Within these ephemeral drainages is a stock pond, about 3/8 of a mile to the northeast from this location. Water well contamination: No, closest stock water wells are about 3/4 of a mile to the east, 7/8 of a mile to the northwest and 1 mile to the northwest from this location. Surface hole will be drilled with freshwater and freshwater muds to 1900'. Surface casing will be cemented to surface from1900'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No Class I stream drainages in the area of review. Mitigation: X Lined reserve pit
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about 1/8 of a mile to the east are unnamed ephemeral tributary drainages to Hardscrabble Creek. Within these ephemeral drainages is a stock pond, about 3/8 of a mile to the northeast from this location. Water well contamination: No, closest stock water wells are about 3/4 of a mile to the east, 7/8 of a mile to the northwest and 1 mile to the northwest from this location. Surface hole will be drilled with freshwater and freshwater muds to 1900'. Surface casing will be cemented to surface from1900'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No Class I stream drainages in the area of review. Mitigation: X Lined reserve pit X Adequate surface casing
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about ¼ of a mile to the east are unnamed ephemeral tributary drainages to Hardscrabble Creek. Within these ephemeral drainages is a stock pond, about 3/8 of a mile to the northeast from this location. Water well contamination: No, closest stock water wells are about 3/4 of a mile to the east, 7/8 of a mile to the northwest and 1 mile to the northwest from this location. Surface hole will be drilled with freshwater and freshwater muds to 1900'. Surface casing will be cemented to surface from1900'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No Class I stream drainages in the area of review. Mitigation: X Lined reserve pit X Adequate surface casing Berms/dykes, re-routed drainage
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about 1/4 of a mile to the east are unnamed ephemeral tributary drainages to Hardscrabble Creek. Within these ephemeral drainages is a stock pond, about 3/8 of a mile to the northeast from this location. Water well contamination: No, closest stock water wells are about 3/4 of a mile to the east, 7/8 of a mile to the northwest and 1 mile to the northwest from this location. Surface hole will be drilled with freshwater and freshwater muds to 1900'. Surface casing will be cemented to surface from1900'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No Class I stream drainages in the area of review. Mitigation: X Lined reserve pit X Adequate surface casing Berms/dykes, re-routed drainage Closed mud system
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about ¼ of a mile to the east are unnamed ephemeral tributary drainages to Hardscrabble Creek. Within these ephemeral drainages is a stock pond, about 3/8 of a mile to the northeast from this location. Water well contamination: No, closest stock water wells are about 3/4 of a mile to the east, 7/8 of a mile to the northwest and 1 mile to the northwest from this location. Surface hole will be drilled with freshwater and freshwater muds to 1900'. Surface casing will be cemented to surface from1900'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No Class I stream drainages in the area of review. Mitigation: X Lined reserve pit X Adequate surface casing Berms/dykes, re-routed drainage Closed mud system Off-site disposal of solids/liquids (in approved facility)
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about 1/4 of a mile to the east are unnamed ephemeral tributary drainages to Hardscrabble Creek. Within these ephemeral drainages is a stock pond, about 3/8 of a mile to the northeast from this location. Water well contamination: No, closest stock water wells are about 3/4 of a mile to the east, 7/8 of a mile to the northwest and 1 mile to the northwest from this location. Surface hole will be drilled with freshwater and freshwater muds to 1900'. Surface casing will be cemented to surface from1900'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No Class I stream drainages in the area of review. Mitigation: X Lined reserve pit X Adequate surface casing Berms/dykes, re-routed drainage Closed mud system Off-site disposal of solids/liquids (in approved facility) Other: Other:
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil based mud system on main hole. Brine water in the horizontal lateral. High water table: No high water table anticipated. Surface drainage leads to live water: Yes, from this location, about 1/8 of a mile to the north and about ¼ of a mile to the east are unnamed ephemeral tributary drainages to Hardscrabble Creek. Within these ephemeral drainages is a stock pond, about 3/8 of a mile to the northeast from this location. Water well contamination: No, closest stock water wells are about 3/4 of a mile to the east, 7/8 of a mile to the northwest and 1 mile to the northwest from this location. Surface hole will be drilled with freshwater and freshwater muds to 1900'. Surface casing will be cemented to surface from1900'. Porous/permeable soils: No, sandy clay soils. Class I stream drainage: No Class I stream drainages in the area of review. Mitigation: X Lined reserve pit X Adequate surface casing Berms/dykes, re-routed drainage Closed mud system Off-site disposal of solids/liquids (in approved facility)

Soils/Vegetation/Land Use

(possible concerns)
Steam crossings: No, stream crossing required.
High erosion potential: No, moderate cut, up to 13.7' and moderate fill, up to 14.3',
required
Loss of soil productivity: No, location will be restored after drilling, if nonproductive. If
productive unused portion of drillsite will be reclaimed
Unusually large wellsite: <u>Large wellsite</u> , 500'X270' location size required
Damage to improvements: Slight, surface use is cultivated land.
Conflict with existing land use/values: Slight
Mitigation
Avoid improvements (topographic tolerance)Exception location requested
Exception location requested _X Stockpile topsoil
Stockpile topsoil Stream Crossing Permit (other agency review)
Stream crossing remit (other agency review) _X_Reclaim unused part of wellsite if productive
Special construction methods to enhance reclamation
X Other: Requires DEQ General Permit for Storm Water Discharge Associated
with Construction Activity, under ARM 17.30.1102(28).
man ochoniadaen ridanny anader rinam rridon rida (20).
Comments: _Access will use existing county road, County Road 335. A new access
road will be built into this location off the existing county road, about 3224'. A lined
reserve pit will be used to hold drill cuttings and drilling fluids. Free liquids in the reserve
pit will be trucked to a Class II Disposal. Cuttings will be allowed to dry in the reserve
pit, after drying the cuttings will be buried in the lined reserve pit. No special concerns.
Health Hazards/Noise
(possible concerns)
Proximity to public facilities/residences: None within 1 mile of this location. Doran
School about 1.25 miles to the northeast from this location
Possibility of H2S: Slight H2S possible.
Size of rig/length of drilling time: Triple drilling rig 30 to 40 days drilling time.
Mitigation:
_X Proper BOP equipment
Topographic sound barriers
H2S contingency and/or evacuation plan
Special equipment/procedures requirements
Other:
Comments: Adequate surface casing and operational BOP should mitigate
any problems. No concerns
Wildlife/recreation
(possible concerns)
Proximity to sensitive wildlife areas (DFWP identified): None identified.
Proximity to recreation sites: None identified.
Creation of new access to wildlife habitat: No
Conflict with game range/refuge management: No

Richiand Coliniv Pining Piover Interior Lease Lem Whooning Crane and Pallig
Richland County, Piping Plover, Interior Lease Tern, Whooping Crane and Pallid Sturgeon. Candidate species is the Greater Sage Grouse.
Mitigation:
Avoidance (topographic tolerance/exception)
Other agency review (DFWP, federal agencies, DSL)
Screening/fencing of pits, drillsite
Other:
Comments:Private surface lands, cultivated field. No concerns.
Historical/Cultural/Paleontological
(possible concerns)
Proximity to known sites: None identified.
Mitigation
avoidance (topographic tolerance, location exception)
other agency review (SHPO, DSL, federal agencies)
Other:
Comments: On private cultivated surface lands. No concerns.
0 11/5
Social/Economic
(naggible concerns)
(possible concerns)
Substantial effect on tax base
Substantial effect on tax base Create demand for new governmental services
Substantial effect on tax base Create demand for new governmental services Population increase or relocation
Substantial effect on tax base Create demand for new governmental services
Substantial effect on tax base Create demand for new governmental services Population increase or relocation
Substantial effect on tax base Create demand for new governmental services Population increase or relocation
Substantial effect on tax base Create demand for new governmental services Population increase or relocation
Substantial effect on tax base Create demand for new governmental services Population increase or relocation Comments: No concerns Remarks or Special Concerns for this site
Substantial effect on tax base Create demand for new governmental services Population increase or relocation Comments: No concerns Remarks or Special Concerns for this site Well is a wildcat, single lateral Bakken Formation horizontal well,
Substantial effect on tax base Create demand for new governmental services Population increase or relocation Comments: No concerns Remarks or Special Concerns for this site
Substantial effect on tax base Create demand for new governmental services Population increase or relocation Comments: No concerns Remarks or Special Concerns for this site Well is a wildcat, single lateral Bakken Formation horizontal well,
Substantial effect on tax base Create demand for new governmental services Population increase or relocation Comments: No concerns Remarks or Special Concerns for this site Well is a wildcat, single lateral Bakken Formation horizontal well,
Substantial effect on tax base Create demand for new governmental services Population increase or relocation Comments: No concerns Remarks or Special Concerns for this site Well is a wildcat, single lateral Bakken Formation horizontal well, 19,468'MD/9,939'TVD. Summary: Evaluation of Impacts and Cumulative effects
Substantial effect on tax base Create demand for new governmental services Population increase or relocation Comments: No concerns Remarks or Special Concerns for this site Well is a wildcat, single lateral Bakken Formation horizontal well, 19,468'MD/9,939'TVD.
Substantial effect on tax base Create demand for new governmental services Population increase or relocation Comments: No concerns Remarks or Special Concerns for this site Well is a wildcat, single lateral Bakken Formation horizontal well, 19,468'MD/9,939'TVD. Summary: Evaluation of Impacts and Cumulative effects
Substantial effect on tax base Create demand for new governmental services Population increase or relocation Comments: No concerns Remarks or Special Concerns for this site Well is a wildcat, single lateral Bakken Formation horizontal well, 19,468'MD/9,939'TVD. Summary: Evaluation of Impacts and Cumulative effects No long term impacts expected. Some short term surface impacts will occur.
Substantial effect on tax base Create demand for new governmental services Population increase or relocation Comments: No concerns Remarks or Special Concerns for this site Well is a wildcat, single lateral Bakken Formation horizontal well, 19,468'MD/9,939'TVD. Summary: Evaluation of Impacts and Cumulative effects

human environment, and (does/ $\underline{\text{does not}}$) require the preparation of an environmental impact statement.
Prepared by (BOGC):_/s/Steven Sasaki(title:)_Chief Field Inspector Date:_October 5, 2010
Date. October 5, 2010
Other Persons Contacted:
_Montana Bureau of Mines and Geology, GWIC website
(Name and Agency) Richland County water wells
(subject discussed) October 4, 2010
(date)
US Fish and Wildlife, Region 6 website (Name and Agency) ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES MONTANA COUNTIES, Richland County (subject discussed)
_ <u>October 5, 2010</u> (date)
If location was inspected before permit approval: Inspection date: Inspector: Others present during inspection: